

YTVI Timer Too Close

- <https://klipper.discourse.group/t/timer-too-close/6634>
- <https://docs.siboor.com/siboor-trident-june/faq-oct-17/new-cb2-timer-too-close>

Hardware

- Kopfboard zu heiß ?

TRSYNC_TIMEOUT

- TRSYNC_TIMEOUT = 0.05 > mcu.py
- https://github.com/rootiest/zippy-klipper_config/blob/master/scripts/mcu_timing.sh
- <https://klipper.discourse.group/t/allow-changing-trsync-timeout-in-printer-cfg-or-permanently-change-it-to-0-05/10467>

Abhilfe 1 - nice

- <https://github.com/Dids/klipper-priority-fix>
- KLIPPY_PROCESS_NAME = "klippy.py"
- KLIPPY_NICE_VALUE = -20
- `renice -n {KLIPPY_NICE_VALUE} -p {pid} || sudo renice -n {KLIPPY_NICE_VALUE} -p {pid}`

Abhilfe 2 - chrt

- <https://github.com/Dids/klipper-priority-fix>
- `chrt -verbose -all-tasks -pid 1 {pid} || sudo chrt -verbose -all-tasks -pid 1 {pid}`

From:

<https://www.drklipper.de/> - **Dr. Klipper Wiki**

Permanent link:

https://www.drklipper.de/doku.php?id=klipper_faq:yarvi_timer_too_close

Last update: **2025/02/06 14:21**

